

1. The whirling drill bit follows a 3D path around a block of metal becomes a part


Oragon State University Computer Graphics

In the Beginning, All Manufacturing was "Subtractive"

2

1. The whirling drill bit follows a 3D path around a block of metal, wax, or wood
2. Chips fly
3. A block of metal becomes a part

1 2







3




The 3D Printing Geometry File 3D Printers are fed a file called an "STL File", which lists all the triangles in the object. All 3D CAD-ish systems (as well as TinkerCad, Thingiverse, and Blender) can produce this type of file for you. solid In this particular file, these coordinates facet normal 0.00 0.00 -1.00 were in units of inches. outer loop vertex -2.000000 -2.000000 0.250000 vertex -1.980000 -1.980000 0.250000 Some 3D Printers still use inches, but vertex -1.980000 -2.000000 0.250000 most now seem to use millimeters. endloop endfacet Check! It matters! facet normal 0.00 0.00 -1.00 outer loop Note: there are 25.4 mm/inch vertex -2.000000 -2.000000 0.250000 vertex -2.000000 -1.980000 0.250000 vertex -1.980000 -1.980000 0.250000 If you sent this file to a millimeterendloop based 3D printer, the part would come endfacet out very, very tiny! © Oregon Stat University endsolid Computer Graphics

6





8




Object Rules for 3D Printing


2. The object must be a legal solid. It must have a definite inside and a definite outside. It can't have any missing face pieces.

Originalizate University Computer Graphics


Definite inside and outside" is sometimes called "Two-manifold" or "Watertight"


10








11 12






















































31

R

